# **True-Color Fixed VIEW** Auto Darkening Filter Lens

- Enhanced visible spectrum, optimal clarity
- · Power supplied by Solar and Lithium Battery
- Auto-on / Auto-off circuitry
- Switching speed 3/10,000 sec (0.3 ms)

### 11121, 11122, 11123, 11124

- Thin design: fits all 2" x 4.25" welding helmets
- 2 Independent Arc Sensors. Thickness 0.2" (5mm)
- Viewing area of 5.15 square inch. 3.62" x 1.42"
- 11121, 11122 CE Classification: 1/1/1/1
- 11123, 11124 CE Classification: 1/1/1/2

#### 11125

- Thin design: fits all 4.5" x 5.25" welding helm
- 4 Independent Arc Sensors. Thickness 0.28"
- Viewing area of 9.3 square inch. 3.94" x 2.36
- Optical Clarity Classification: 1/1/1/1
  - Accuracy of Vision
  - Diffusion of Light
  - Consistent Shade
  - Angular Dependence



Clear True-Color Blue HD Technology

> Alleviates eye and neck fatigue



11122



2 cover lens included

2 Year Warranty

Meets ANSI Z87.1, CSA Z94.3, CE EN 379 Standards

nets		AUTO DARKENING	
(7mm)	MISSISSIPPER STATE	11121-WC 3/10	CE X LD &
6"			

\* Sold in units of 1

UPC #	Size	Filter Fixed	View Area	Description	CE Classification	Retail QTY*	Retail Pack	Master Pack
11121	2" x 4.25" x .20" (5mm)	9	3.62" x 1.42" (5.15 sq in)	True-Color	1/1/1/1	1	10	20
11122	2" x 4.25" x .20" (5mm)	10	3.62" x 1.42" (5.15 sq in)	True-Color	1/1/1/1	1	10	20
11123	2" x 4.25" x .20" (5mm)	11	3.62" x 1.42" (5.15 sq in)	True-Color	1/1/1/2	1	10	20
11124	2" x 4.25" x .20" (5mm)	12	3.62" x 1.42" (5.15 sq in)	True-Color	1/1/1/2	1	10	20
11125	4.5" x 5.25" x .28" (7mm)	10	3.94" x 2.36" (9.30 sq in)	True-Color	1/1/1/1	1	10	5

## **Instruction For Use**

- » Install the filter and protective plate into the suitable welding helmet.
- The solar cell and light sensor must be fully exposed and be sure the arc light can be received fully by solar cell and sensor.
- Then strike the arc, the filter will be darken immediately.

### Warning

- » Replace damaged parts to avoid serious injury.
- Avoid heavy knock to break the filter.
- » Do not immerse filter into water or other liquid.
- » Use only at 14°F (-10°C) 149°F (65°C).
- » If the filter is not be used for a long period of time, pack the filter in the box or store in a dark place.
- » Storage temperature is -4°F (-20°C) 185°F (85°C).

**A** WARNING: This product can expose you to chemicals including Dichloromethane (Methylene chloride), which is known to the State of California to cause cancer, and Bisphenol A (BPA), which is known to the State of California to cause birth defects and/or other reproductive harm. For more information go to www.P65Warnings.ca.gov.



Weldcote Sales & Corporate Offices, Kings Mountain, NC phone: 877-866-4115, 704-739-4115, fax: 704-739-6116

Weldcote Warehouse & Sales, Ontario, CA phone: 866-923-2167, fax: 909-923-7016

# www.weldcote.com

Weldcote Abrasive & Manufacturing Distribution Center & Training, Niles, IL

phone: 224-998-2600, 888-258-0121

fax: 224-998-2649